



HYTORC HY-.7 MXT SA

PRESSURE IN PSI	PRESSURE/TORQUE CONVERSION CHART			PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	125	17	169	104
1600	132	18	179	110
1800	146	20	198	124
2000	161	22	218	138
2200	177	24	240	152
2400	194	27	263	166
2600	210	29	285	179
2800	227	31	308	193
3000	244	34	331	207
3200	260	36	352	221
3400	276	38	374	235
3600	293	41	397	248
3800	309	43	419	262
4000	325	45	441	276
4200	342	47	464	290
4400	358	50	485	304
4600	374	52	507	317
4800	391	54	530	331
5000	407	56	552	345
5200	423	59	573	359
5400	440	61	596	373
5600	456	63	618	386
5800	472	65	640	400
6000	489	68	663	414
6200	505	70	685	428
6400	522	72	708	442
6600	538	74	729	455
6800	554	77	751	469
7000	571	79	774	483
7200	587	81	796	497
7400	603	83	817	511
7600	619	86	839	524
7800	635	88	861	538
8000	651	90	882	552
8200	667	92	904	566
8400	684	95	927	580
8600	700	97	949	593
8800	716	99	971	607
9000	733	101	994	621
9200	748	103	1014	635
9400	764	106	1036	649
9600	780	108	1057	662
9800	796	110	1079	676
10000	812	112	1101	690

This chart supercedes all prior version regarding this tool 03/31/2008

Southwest Texas 4802 Baldwin Blvd. Corpus Christi 78408 361-888-5080	West Texas 3508 S County Rd 1290 Odessa, TX 78765 432-561-8481	Main Office 12420 Texaco Rd Houston, TX 77013 713-453-6677	Southeast Texas 2484 W Cardinal #4 Beaumont, TX 77705 409-840-9699	Central & East Texas 7900 Rodeo Trl. #500 Mansfield, TX 76063 682-334-2679
--	--	--	--	--