



HYTORC HY-.7MXT

PRESSURE IN PSI	PRESSURE.TORQUE CONVERSION CHART			PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	118	16	160	104
1600	126	17	171	110
1800	143	20	194	124
2000	160	22	217	138
2200	176	24	239	152
2400	193	27	262	166
2600	209	29	283	179
2800	226	31	306	193
3000	242	33	328	207
3200	259	36	351	221
3400	275	38	373	235
3600	292	40	396	248
3800	308	43	418	262
4000	325	45	441	276
4200	342	47	464	290
4400	359	50	487	304
4600	375	52	508	317
4800	392	54	531	331
5000	409	57	554	345
5200	425	59	576	359
5400	442	61	599	373
5600	458	63	621	386
5800	475	66	644	400
6000	491	68	666	414
6200	508	70	689	428
6400	524	72	710	442
6600	541	75	733	455
6800	557	77	755	469
7000	574	79	778	483
7200	591	82	801	497
7400	608	84	824	511
7600	625	86	847	524
7800	642	89	870	538
8000	659	91	893	552
8200	675	93	915	566
8400	691	96	937	580
8600	706	98	957	593
8800	722	100	979	607
9000	738	102	1000	621
9200	755	104	1023	635
9400	772	107	1047	649
9600	788	109	1068	662
9800	805	111	1091	676
10000	822	114	1114	690

This chart supercedes all prior version regarding this tool 03/31/2008

Southwest Texas 4802 Baldwin Blvd. Corpus Christi 78408 361-888-5080	West Texas 3508 S County Rd 1290 Odessa, TX 78765 432-561-8481	Main Office 12420 Texaco Rd Houston, TX 77013 713-453-6677	Southeast Texas 2484 W Cardinal #4 Beaumont, TX 77705 409-840-9699	Central & East Texas 7900 Rodeo Trl. #500 Mansfield, TX 76063 682-334-2679
--	--	--	--	--