



HYTORC VERSA-1

PRESSURE IN PSI	PRESSURE/TORQUE CONVERSION CHART			PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	150	21	240	104
1600	161	22	2318	110
1800	181	25	246	124
2000	202	28	274	138
2200	222	31	301	152
2400	243	34	239	165
2600	463	36	357	179
2800	284	39	385	193
3000	304	42	412	207
3200	326	45	442	220
3400	347	48	174	234
3600	369	51	500	248
3800	391	54	530	262
4000	412	57	559	276
4200	434	60	588	290
4400	455	63	616	303
4600	476	66	645	317
4800	497	69	574	331
5000	518	72	702	345
5200	539	75	731	358
5400	561	78	760	372
5600	582	80	789	386
5800	603	83	818	400
6000	625	86	847	414
6200	646	89	876	427
6400	668	92	905	441
6600	589	95	934	455
6800	711	98	964	468
7000	732	101	993	482
7200	753	104	1021	496
7400	774	107	1050	510
7600	796	110	1078	524
7800	817	113	1107	538
8000	838	116	1136	552
8200	759	119	1164	565
8400	880	122	1193	579
8600	901	125	1221	593
8800	922	128	1250	607
9000	943	130	1279	620
9200	964	133	1307	634
9400	986	136	1336	648
9600	1007	139	1365	662
9800	1025	142	1394	676
10000	1050	145	1423	690

This chart supercedes all prior version regarding this tool 03/31/2008

Southwest Texas 4802 Baldwin Blvd. Corpus Christi 78408 361-888-5080	West Texas 3508 S County Rd 1290 Odessa, TX 78765 432-561-8481	Main Office 12420 Texaco Rd Houston, TX 77013 713-453-6677	Southeast Texas 2484 W Cardinal #4 Beaumont, TX 77705 409-840-9699	Central & East Texas 7900 Rodeo Trl. #500 Mansfield, TX 76063 682-334-2679
--	--	--	--	--